

Filter Lenses for Protection Against Radiant Energy

Operations	Electrode Size 1/32 in.	Arc Current	Minimum(*) Protective Shade
Shielded metal arc welding	Less than 3 .....	Less than 60 ...	7
	3-5 .....	60-160 .....	8
	5-8 .....	160-250 .....	10
	More than 8 .....	250-550 .....	11
Gas metal arc welding and flux cored arc welding		less than 60 ...	7
		60-160 .....	10
		160-250 .....	10
		250-500 .....	10
Gas Tungsten arc welding		less than 50 ...	8
		50-150 .....	8
		150-500 .....	10
Air carbon Arc cutting	(Light) .....	less than 500 ..	10
	(Heavy) .....	500-1000 .....	11
Plasma arc welding		less than 20 ...	6
		20-100 .....	8
		100-400 .....	10
		400-800 .....	11
Plasma arc cutting	(light) (**) .....	less than 300 ..	8
	(medium) (**) .....	300-400 .....	9
	(heavy) (**) .....	400-800 .....	10
Torch brazing		.....	3
Torch soldering		.....	2
Carbon arc welding		.....	14

Filter Lenses for Protection Against Radiant Energy

Operations	Plate thickness-inches	Plate thickness-mm	Minimum(*) Protective Shade
<b>Gas Welding:</b>			
Light	Under 1/8 .....	Under 3.2 .....	4
Medium	1/8 to 1/2 .....	3.2 to 12.7 .....	5
Heavy	Over 1/2 .....	Over 12.7 .....	6
<b>Oxygen cutting:</b>			
Light	Under 1 .....	Under 25 .....	3
Medium	1 to 6 .....	25 to 150 .....	4
Heavy	Over 6 .....	Over 150 .....	5

Footnote(\*) As a rule of thumb, start with a shade that is too dark to see the weld zone. Then go to a lighter shade which gives sufficient view of the weld zone without going below the minimum. In oxyfuel gas welding or cutting where the torch produces a high yellow light, it is desirable to use a filter lens that absorbs the yellow or sodium line in the visible light of the (spectrum) operation.

Footnote(\*\*) These values apply where the actual arc is clearly seen. Experience has shown that lighter filters may be used when the arc is hidden by the workpiece.

Reference: 29 CFR 1910.133(a) (5)