IPS WELD-ON

MATERIAL SAFETY DATA SHEET

Date Revised: JAN 2005 Supersedes: AUG 2004

Information on this form is furnished solely for the purpose of compliance with the Occupational Safety and Health Act and shall not be used for any other purpose. IPS Corporation urges the customers receiving this Material Safety Data Sheet to study it carefully to become aware of the hazards, if any, of the product involved. In the interest of safety, you should notify your employees, agents and contractors of the information on this sheet.

SECTION I

MANUFACTURER'S NAME

IPS Corporation **ADDRESS**

17109 S. Main St., Gardena, CA 90248

Transportation Emergencies:

CHEMTREC: (800) 424-9300 Medical Emergencies:

3 E COMPANY (24 Hour No.) (800) 451-8346

Business: (310) 898-3300

CHEMICAL NAME and FAMILY

Mixture of Organic Solvents

PVC/CPVC Cleaner and Adhesive Bonding Primer

TRADE NAME:

WELD-ON C-65 Cleaner for Plastic Pipe

FORMULA: Proprietary

SECTION II - HAZARDOUS INGREDIENTS

None of the ingredients below are listed as carcinogens by IARC, NTP or OSHA CAS# APPROX % ACGIH-TLV ACGIH-STEL OSHA-PEL **OSHA-STEL** 200 PPM Methyl Ethyl Ketone (MEK) 78-93-3 3 - 13* 300 PPM 200 PPM 300 PPM Acetone 67-64-1 80 - 95 750 PPM 1000 PPM 750 PPM 1000 PPM

Cyclohexanone 108-94-1 1 - 7 20 PPM Skin 50 PPM 50 PPM Skin

All of the constituents of Weld-On adhesive products are listed on the TSCA inventory of chemical substances maintained by the US EPA, or are exempt from that listing.

* Title III Section 313 Supplier Notification: This product contains toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-to-Know Act of 1986 and of 40CFR372. This information must be included in all MSDS's that are copied and distributed for this material.

BULK SHIPPING INFORMATION / CONTAINERS LARGER THAN ONE LITER		SPECIAL HAZARD DESIGNATIONS			
DOT Shipping Name:	Flammable Liquid N.O.S.		HMIS	NFPA	HAZARD RATING
	(Acetone, Methyl Ethyl Ketone)	HEALTH:	2	2	0 - MINIMAL
DOT Hazard Class:	3	FLAMMABILITY:	3	3	1 - SLIGHT
Identification Number:	UN 1993	REACTIVITY:	0	1	2 - MODERATE
Packaging Group:	II	PROTECTIVE			3 - SERIOUS
Label Required:	Flammable Liquid	EQUIPMENT:	B - H		4 - SEVERE
SHIPPING INFORMATIO	N FOR CONTAINERS LESS THAN ONE LITER	B = Eve Hand/Skin (fo	r normal solvent-	welding small	spill clean-up activities

DOT Shipping Name: Consumer Commodity

DOT Hazard Class: ORM-D

H = Eye, Hand/Skin, Respiratory Protection and Impermeable Apron (splash/

SECTION III - PHYSICAL DATA

		-	
APPEARANCE	ODOR	BOILING POINT (°F/°C)	
Colorless, thin liquid	Ketone	133°F (57°C) Based on first boiling component:	
		Acetone	
SPECIFIC GRAVITY @ 73°F ± 3.6° (23°C ± 2°)	VAPOR PRESSURE (mm Hg.)	PERCENT VOLATILE BY VOLUME (%)	
Typical 0.798 ± 0.040	190 mm Hg. based on first boiling	100%	
	component, Acetone @ 68°F (20°C)		
VAPOR DENSITY (Air = 1)	EVAPORATION RATE (BUAC = 1)	SOLUBILITY IN WATER	
2.0	6-11	Completely soluble in water.	

VOC STATEMENT: VOC as manufactured: 800 Grams/Liter (g/l). A reactive diluent per SCAQMD Rule 1168. Maximum VOC emission when applied and tested per SCAQMD Rule 1168, Test Method 316A: 550 g/l.

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT		FLAMMABLE LIMITS	LEL	UEL
	-6°F (-21°C) T.C.C. Based on Acetone	(PERCENT BY VOLUME)	2.1	13.0

FIRE EXTINGUISHING MEDIA

Ansul "Purple K" potassium bicarbonate dry chemical, any appropriately sized ABC dry chemical, carbon dioxide or foam extinguisher can be used for small fires. Use of a water fog by trained personnel can extinguish small/large fires.

SPECIAL FIRE FIGHTING PROCEDURES

Evacuate enclosed areas. Stay upwind. Close quarters or confined spaces require self-contained breathing apparatus, positive pressure mask or airline mask. Use of a water fog by trained personnel can extinguish small/large fires and avoid water flow or water streams/spray distributing burning material or contaminated water over a large area or into sewers or storm drains. Use water spray to cool containers, to flush spills from source of ignition and to disperse vapors.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Fire hazard because of low flash point and high volatility. Vapors are heavier than air and may travel to source(s) of ignition at or near ground or lower level(s) and flash back.

æ-d

SECTION V - HEALTH HAZARD DATA PRIMARY ROUTES OF ENTRY: Ingestion Inhalation Skin Contact Eye Contact EFFECT OF OVEREXPOSURE ACUTE: Inhalation: Severe overexposure may result in nausea, dizziness, headache. Can cause drowsiness, irritation of eyes and nasal passages. Skin Contact: Skin irritant. Liquid contact may remove natural skin oils resulting in skin irritation. Dermatitis may occur with prolonged contact. Skin Absorption: Prolonged or widespread exposure may result in the absorption of harmful amounts of material. Eye Contact: Overexposure may result in severe eye injury with corneal or conjuctival inflammation on contact with the liquid. Vapors slightly uncomfortable Moderately toxic. May cause nausea, vomiting, diarrhea. May cause mental sluggishness. Ingestion: CHRONIC: High vapor concentrations may produce CNS depression. Depression may be evidenced by headache, dizziness and nausea. Aspirated material may cause severe lung damage and present a significant hazard. REPRODUCTIVE EFFECTS TERATOGENICITY MUTAGENICITY EMBRYOTOXICITY SENSITIZATION TO PRODUCT SYNERGISTIC PRODUCTS N. AP. N. AP. N. AP. MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: Individuals with pre-existing diseases of the eyes, skin or respiratory system may have increased susceptibility to the toxicity of excessive exposures. **EMERGENCY AND FIRST AID PROCEDURES** If overcome by vapors, remove to fresh air and if breathing stopped, give artificial respiration. If breathing is difficult, give oxygen. Call Inhalation: Eye Contact: Flush eyes with plenty of water for 15 minutes and call a physician. Remove contaminated clothing and shoes. Wash skin with plenty of soap and water for at least 15 minutes. If irritation develops, get Skin Contact: Give 1 or 2 glasses of water or milk. Do not induce vomiting. Call physician or poison control center immediately. Ingestion: SECTION VI - REACTIVITY STABILITY UNSTABLE CONDITIONS TO AVOID STABLE Keep away from heat, sparks, open flame and other sources of ignition. INCOMPATIBILITY (MATERIALS TO AVOID) Caustics, ammonia, inorganic acids, chlorinated compounds, strong oxidizers and isocyanates. HAZARDOUS DECOMPOSITION PRODUCTS When forced to burn, this product gives out carbon monoxide and carbon dioxide. HAZARDOUS MAY OCCUR CONDITIONS TO AVOID WILL NOT OCCUR **POLYMERIZATION** Keep away from heat, sparks, open flame and other sources of ignition. **SECTION VII - SPILL OR LEAK PROCEDURES** STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Eliminate all ignition sources. Avoid breathing of vapors. Keep liquid out of eyes. Flush with large amount of water. Contain liquid with sand or earth. Absorb with sand or nonflammable absorbent material and transfer into steel drums for recovery or disposal. Prevent liquid from entering drains. WASTE DISPOSAL METHOD Follow local, State and Federal regulations. Consult disposal expert. Can be disposed of by incineration. Excessive quantities should not be permitted to enter drains. Empty containers should be air dried before disposing. Hazardous Waste Code (CA): 214. SECTION VIII - SPECIAL PROTECTION INFORMATION RESPIRATORY PROTECTION (Specify type) Atmospheric levels should be maintained below established exposure limits contained in Section II. If airborne concentrations exceed those limits, use of a NIOSH approved organic vapor cartridge respirator with full face-piece is recommended. The effectiveness of an air purifying respirator is limited. Use it only for a single short-term exposure. For emergency and other conditions where short-term exposure guidelines may be exceeded, use an approved positive pressure self-contained breathing apparatus. Use only with adequate ventilation. Do not use in close quarters or confined spaces. Open doors and/or windows to ensure airflow and air changes. Use local exhaust ventilation to remove airborne contaminants from employee breathing zone and to keep contaminants below levels listed in Section II. Use only explosion-proof ventilation equipment. PROTECTIVE GLOVES PVA coated rubber gloves for frequent dipping/immersion. Use of latex/nitrile EYE PROTECTION Splashproof chemical goggles. surgical gloves or solvent resistant barrier creme should provide adequate protection when normal solventface shield, safety glasses (spectacles) with brow cement welding practices and procedures are used for making plastic welded pipe joints. guards and side shields, etc. as appropriate for exposure. OTHER PROTECTIVE EQUIPMENT AND HYGIENIC PRACTICES Impervious apron and a source of running water to flush or wash the eyes and skin in case of contact. **SECTION IX - SPECIAL PRECAUTIONS**

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Store in the shade between 40°F - 110°F (5°C - 43.7°C). Keep away from heat, sparks, open flame and other sources of ignition. Avoid prolonged breathing of vapor. Use with adequate ventilation. Avoid contact with eyes, skin and clothing. Train employees on all special handling procedures before they work with this product.

OTHER PRECAUTIONS

Follow all precautionary information given on container label, product bulletins and our solvent cementing literature. All material handling equipment should be electrically grounded.

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of this data or the results to be obtained from the use thereof.

> æ-d Sheet 2 of 2